

Triumph Service Bulletin Index.

This Index covers the Triumph Factory Service Bulletins held by the VMCC Library

They contain valuable information for restorers and historians, contact the VMCC for copies. Using the Reference No:

Year	Bulletin	Description	Ref
1949	24-May-49	Notice to Overseas Dealers on the Trophy Model.	TC101
1950	1	Twins. Low Oil Pressure Trouble Shooting.	824
1950	24	Tiger 100 Tuning.	551
1950	33	1949 Spares Supplement	554
1950	37	Air filters.	825
1950	39	TR5 Trophy Technical Data.	826
1950	40	Trophy Modifications for Scrambles.	827
1950	45	Trophy Gear Ratios & Engine Revs.	828
1950	53	Thunderbird Sprockets. Solo and Sidecar.	829
1950	61	T110 Thunderbird Lack of Speed.	830
1951	01-Feb-51	Suggestions for the Preparation of Triumphs for Racing at Daytona	TC102
1951	08-Mar-51	3 Month Guarantee introduced throughout USA	TC103
1951	24-May-51	Use and conversion of the TR5 Trophy Model for Competition. Includes detailed Parts List and Instructions.	TC104
1951	20-Jul-61	Special Triumph Service Tools including price list	TC105
1951	20-Sep-51	Modification of the 1951 Thunderbird Carburettor Slide to cure poor running.	TC106
1951	02-Oct-51	Assembly and Adjustment of Triumph Forks	TC107
1951	08-Nov-51	Lucas and Smiths Guarantee Claims. Where to Send Failed Units.	TC108
1951	05-Dec-51	Triumph Racing Success and Preparation of a Triumph Racer for the Daytona Beach Races	TC109
1951	69	Trophy Model. Modifications for Scrambles.	831
1951	70	Oil Consumption Taper Piston Ring Fitted.	832
1951	80	All Models except 3T New Tipped Tappets.	833
1952	04-Feb-52	Air Cleaner must be used with SU Carburettor. Thunderbird and 6T	TC110
1952	03-Apr-52	Clutch Plate exchange plan for T414 Clutch Plates.	TC111
1952	09-Apr-52	Triumph Accessories Now Available. Handlebars, Kickstarter, Front Fender, S.U. Carb Parts	TC112

1952	23-Jun-52	Positive Earth Introduced on all machines. Whitworth sizes of Fasteners.	TC113
1952	09-Sep-52	Tappet Guides on late "Tigers". Cast Iron Tappet Blocks in Alloy Engines. 1952 Models	TC114
1952	11-Sep-52	Special Rubber Fork Gaiter, Waterproof Spark Plug Terminal, Ignition Lock for Road Models. Accessories Supplied	TC115
1952	27-Oct-52	Uncrating and Setting Up New Triumph Motorcycles. Detailed article	TC116
1952	10-Nov-52	Tuning the 1952-53 Triumph Thunderbird for Best Performance. Problems with some machines.	TC117
1952	18-Nov-52	Special Triumph Service Tools. Seven Essential Factory Tools.	TC118
1952	20-Nov-52	Complete List of Triumph Decals. Decals for Shop Décor and Machine Decals.	TC119
1952	03-Dec-52	Black Thunderbirds. Thunderbirds to be supplied to the USA in All Black Finish or Standard Blue	TC120
1952	97	Tiger 100 Alloy Engine New Tappet Blocks and Cover Tubes	834
1952	106	SU Carburettor. Changes to Improve Performance.	835
1953	12-Jan-53	Immediate availability of the latest 1953 type parts for converting earlier models to 1953 specification.	TC121
1953	17-Jan-53	Triumph's Success in Competition and Preparation of Racing Machines for Daytona Beach. Amazing Document!	TC122
1953	06-Feb-53	Availability of Triumph Racing Kits. Availability and Changes to the CP100 Racing Kit.	TC123
1953	07-Feb-53	Procedure for Assembling the Triumph Gearbox 1950-1953 Type.	TC124
1953	07-Feb-53	Cleaning and Checking the S.U. Carburettor. Service Sheet.	TC125
1953	10-Feb-53	Lubrication Notes. Oil Grades and Quantities to use.	TC126
1953	10-Feb-53	Dimensional Data for Spoking Triumph Wheels. Very Useful Document.	TC127
1953	06-Mar-53	Latest Replacement Parts Book and Supplement, Service B #103. Description only.	TC128
1953	07-Apr-53	1953 A, C Equipped 5T models instructions to Dealers. Service B.	TC129
1953	28-Apr-53	Need to Push Sales of Blue Finished Thunderbirds.	TC130
1953	28-Apr-53	Ramp Type Camshafts E3275. Asterix Marked Crankcases indicate fitment of new E3275 Camshafts. Not T100/C Machines.	TC131
1953	12-May-53	1953 Cush Drive Conversion Kit. Conversion Kit for earlier models to 1953 Specification.	TC132
1953	11-Aug-53	Lucas Conversion Kit to Convert A.C. 5T Models to the latest Specification Free Kit for the Speed Twin.	TC133
1953	13-Aug-53	Tires. Freight Paid on Lots of Ten or Over. Offer for Dunlop Tires.	TC134
1953	14-Aug-53	Instructions for Installing the Triumph Racing 'Q' Cams. Detailed Instructions	TC135
1953	25-Nov-53	New Parts and Accessories. US made Parts and Factory Parts.	TC136
1953	07-Dec-53	New Layshaft Second Gear and High Gears of Improved Design. New Parts for 1954 Models.	TC137
1953	11-Dec-53	Maintenance Notes on the Triumph Terrier T15 Model. Detailed Instructions	TC138
1953	109	Fuel. Modifications for Higher Octane Fuel.	836
1953	110	Tiger 100C Carburettor Settings for Racing.	837
1953	111	Ramp Camshafts E3275. (Wheel Marking with Engine Number).	838
1953	118	Clutch & Gear change. Setting Up.	839

1954	12-Jan-54	Lucas RM13 AC Lighting and Ignition Equipment fitted to Terrier Motorcycles. System Details and Wiring Diagrams	TC201
1954	17-Jan-53	Triumph's Success in Competition and Preparation of Machines for Daytona Beach. Excellent Detailed Document.	TC202
1954	22-Jan-54	Notes on the Preparation of Machines for Daytona Beach Racing. Detailed companion article to the above.	TC203
1954	28-Jan-54	Lucas Regulator Control Box RB107 Parts Description Drawing.	TC204
1954	03-Feb-54	Service Notes on the 1954 Triumph Models. Service Notes. Specifications and New Parts for 1954 Models.	TC205
1954	08-Feb-54	Flat Rate Labour Schedule. Suggested minimum charges and Times for service operations	TC206
1954	15-Mar-54	Lucas Lighting and Ignition Switch Part #31443. Connections on PR8 Switch.	TC207
1954	24-Mar-54	Parts Price Reference Terrier. Initial Replacement Parts Kit A.	TC208
1954	31-Mar-54	Quickly Detachable Rear Wheel for Swinging Arm Models T100/SA and T110. Dealers do not want QD wheel as standard fitment.	TC209
1954	06-May-54	Service Notes on Terrier T15 and Tiger T100 Models. Important Service Document and Snag List for these models.	TC210
1954	09-Jul-54	Jomo Valve Spring. Important Fitting Instructions using spacer washers.	TC211
1954	09-Jul-54	Availability of Heavy Duty Bonded Clutch Plates. #T414AT, CD29 Kit and T999AT Springs	TC212
1954	09-Jul-54	Service Problems for 1954 Triumph Models. Interesting document covering Warranty Issues with 1954 Models.	TC213
1954	28-Jul-54	Service Notes on 1954 Triumph Models. Bulletin 5. Warranty Issues on 1954 Models	TC214
1954	29-Jul-54	Identification of Wiring on T15 and T20 Lightweights. Wiring Colours for Terrier and Cub,	TC215
1954	22-Sep-54	New Heavy Duty Clutch and Brake Cables for Lightweight Models. USA Made.	TC216
1954	29-Sep-54	Top Cylinder Lubricant. Recommendations of Grades. Castrollo.	TC217
1954	01-Nov-54	Specification of Triumph T100R Machine for Class 'C' Racing. Picture and Specification.	TC218
1954	08-Nov-54	New Heavy Duty Clutch Cable for 5T, 6T, T100 and T110 Models. USA Made with Suffix T on Part Numbers	TC219
1954	01-Dec-54	RM13 Alternators as used on Lightweight Models. Increasing Charge Rate for Night Running.	TC220
1954	10-Dec-54	New Type Clutch Sprocket and Bearing for Lightweight Models. Hardened Sprocket and Bearing.	TC221
1954	16-Dec-54	Crankshaft Oil Feed Tube for 1954 Model Twins. Important Service Sheet for engines before #56536	TC222
1954	21-Dec-54	Elimination of Oil Leaks, Service Sheet Covering all Models.	TC223
1954	128	Sidecars and Crash Bars. Warning Sheet.	840
1955	15-Jan-55	S.U. Carburettor Retail Price List.	TC224
1955	15-Jan-55	Confidential Parts Price List. Discount Price List.	TC225
1955	24-Jan-55	Service Notes for Triumph Dealers to be used with Lightweight. Extensive service notes for the Terrier and Cub.	TC226
1955	24-Jan-55	Instruction for using the Triumph Electrical Test Set. Testing the RM13 system on Lightweights.	TC227
1955	01-Feb-55	Notes on the Preparation of Machines for Daytona Beach Racing. Comprehensive Notes on Machine Preparation.	TC228
1955	24-Mar-55	Latest Lucas Retail Price List. Conversion of earlier Speed Twins to 1955 Specification.	TC229
1955	31-Mar-55	New Parts and Accessories Now Available for Immediate Delivery. Interesting document. Small Tanks, Upswept Exhausts etc.	TC230
1955	30-Mar-55	Defective Oil Pump Plungers Fitted to certain Twins. T110 60473	TC231
1955	04-Apr-55	Fitting the New Competition Gas Tank F3869Q to T100 and TR5. Parts required to Fit the Small Competition Tank.	TC232

1955	13-Apr-55	Instructions for Installing "Heavy Duty" Clutch Kit. CD37. Notes on Fitting the Clutch Kit for the Lightweight Models.	TC233
1955	14-Apr-55	Installing Conversion Kit CD36 including RM14 Electrical Equipment. Speed Twin Electrical Upgrade Kit.	TC234
1955	15-Apr-55	Amal Monoblock Carburettor now fitted to 650cc Machines. Wide Ratio Gears now available on Trophy/Scrambler TR5.	TC235
1955	18-Apr-55	Lodge Spark Plugs. Lodge Spark Plug Details for Triumph Models. Lodge Spark Plug Sheets	TC236
1955	17-Jun-55	Thunderbird and Cub Variations in Specification. Small Tank Thunderbirds, Cubs with Upswept Pipes.	TC237
1955	18-Jun-55	Suggested AMA Class "C" Competition Rule Changes for 1956. Interesting Letter from Rod Coates to AMA Members	TC238
1955	02-Aug-55	Warranty and General Service for Lucas, Smiths and Dunlop Items. Rod Coates Hospitalised by Road Accident.	TC239
1955	03-Aug-55	Amal Monoblock Carburettor Parts listing and Prices. Lucas Magneto Parts Issues.	TC240
1955	15-Aug-55	Tuning the T110 Model for Maximum Speed. Service Notes.	TC241
1955	15-Aug-55	Service Notes on 1955 Models. Important Document covering Problems with 1955 Models and Service Solutions	TC242
1955	15-Aug-55	Triumph Electrical Test Set. Testing the Electrical Equipment on the 1955 5T and 6T.	TC243
1955	15-Aug-55	Instructions for Testing and Adjusting All Triumphs Fitted with Lucas D.C. Generators and Regulators. Service Sheet.	TC244
1955	06-Sep-55	Improved Clutch Parts for Lightweight Models. New Parts for 1955 Terrier and Cub Models to be Retro Fitted by Dealers.	TC245
1955	30-Sep-55	Ignition Timing Must be Corrected When Magneto Points are Replaced. Service Sheet.	TC246
1955	06-Oct-55	CD49 Aluminium Cylinder Head Available for T110 Models, Report on Results.	TC247
1955	26-Oct-55	Genuine Triumph Pistons Carried in Stock et Tri-Cor. Part Numbers and Details.	TC248
1955	07-Nov-55	New Low Dealer Prices on Lodge Spark Plugs.	TC249
1955	11-Nov-55	Special Crankshaft Assemblies for Converting all 1946-53 Twins to 1956 Specification. Part numbers and details.	TC250
1955	11-Nov-55	New Accessories, Tools and Parts Kits. Part Numbers and Prices.	TC251
1955	15-Dec-55	End of Year Round-Up of Triumph Owner Competition Successes.	TC252
1955	22-Dec-55	CD38 Rear Brake Anchor Kit for Converting 1954 T100 and T110 to 1955-56 Specification. Failure of earlier Brake Anchors.	TC253
1956	12-Jan-56	Minimum Parts Stock for New Dealers. Replacement Parts and Prices	TC301
1956	17-Jan-56	Instructions for Setting Up and Servicing a 1956 Triumph 6T Model.	TC302
1956	03-Apr-56	Use of Mark II Electrical Test Set. Terrier and Tiger Cub Models.	TC303
1956	04-Apr-56	Use of Mark II Electrical Test Set. All Speed Twin 5T and Thunderbird 6T Models.	TC304
1956	05-Apr-56	New Parts for Early Spring Delivery. Exhausts, Mufflers, Alloy Head, Rev Counters, Dual Carb Kits.	TC305
1956	09-Apr-56	Price Reduction on Genuine Ferodo Brake Linings. All Models	TC306
1956	13-Apr-56	Use of Mark II Electrical Test Set for Lucas DC Generators and Regulators. Wiring Diagrams for All Models	TC307
1956	20-Apr-56	More New Special Parts and Accessories. Safety Bars, Wader Type Contacts, Clutch Band, and Seat Rail.	TC308
1956	01-May-56	Instructions for Fitting Triumph Seat rails CD18 and CD23.	TC309
1956	01-May-56	Instructions for Fitting CD43 Clutch Housing Band.	TC310
1956	01-May-56	Lucas Lighting and Ignition Switch #31443. For Lightweights. Modifications to fit Twins	TC311
1956	01-May-56	Lucas Lighting and Ignition Switch #31443. For Twins. Modifications to fit Lightweights	TC312

1956	01-May-56	Confidential Parts Price List Effective from 1st May 1956.	TC313
1956	03-May-56	Water in Magneto. Remedy Service Sheet.	TC314
1956	03-May-56	Leaking Petrol/Gas Tanks fitted to 1956 TR5 TR6 and T110. Service Sheet. Introduction of Sleeved Washers F3815	TC315
1956	10-May-56	Instructions for Installing "Sleeve Type" Rubber Washers for Tank Mounting Bolts.	TC316
1956	24-May-56	New Connecting Rod with Inset Bearing for Twins. Description Service Sheet.	TC317
1956	28-May-56	Change in Specification for the TR6. New Handlebar Pattern H1014. 19 inch Front Wheel and 8 inch Brake.	TC318
1956	27-Jun-56	Special Puller for Drive Side Inner Cover on Terrier and Cub Models. Puller D342T Instructions.	TC319
1956	14-Sep-56	Index to Service B Range.	TC320
1956	14-Sep-56	Important Service Information on 1956 Twins. Includes Paint Codes.	TC321
1956	02-Oct-56	Genuine Carton Pack Pistons Carried in Stock.. Price List for all Pistons in Varying Compression Ratios and Oversize's.	TC322
1956	12-Oct-56	Accessory Sheet describing the Special Parts and Accessory Catalogue for 1957 Models	TC323
1956	12-Oct-56	Service Notes on 1956 Triumph Lightweight Models.	TC324
1956	16-Oct-56	How to Improve Performance of Terrier and Tiger Cubs for Competition Use. Detailed Instructions.	TC325
1956	17-Oct-56	Castrol Oil. Price List for the various grades of Castrol Oil.	TC326
1956	19-Oct-56	New "Oversize" Ribbed Front Tyre. Prices for the 19 inch Tyre fitted to the 6T, T110 and latest TR6 Models. This may be the Avon SM.	TC327
1956	22-Oct-56	Control Cables from Stock. Fitment, Part Numbers and Prices for all models.	TC328
1956	24-Oct-56	Confidential Dealer Price List on Parts and Accessories for Accessory List 12th Oct 1956.	TC329
1956	05-Dec-56	Swinging Arm Frame Assembly for the 1957 Tiger Cub Model. New Frames to be supplied and New Forks. Price List.	TC330
1956	11-Dec-56	Instructions for Fitting Triumph Mark 2 Air Flow Windshield. CD67.	TC331
1956	12-Dec-56	Sixth Annual Triumph Dealer School to be Held at Tri-Cor's New Premises. Edward Turner to Attend.	TC332
1956	13-Dec-56	Special Triumph Factory Service Tools. Description and Price List.	TC333
1956	148	Terrier & Tiger Cub Oil Pump Modifications.	841
1956	170	T100 Twin Carb Splayed Port Head Conversion. (Important)	842
1957	19-Dec-56	Identifying the Wiring on 1957 T20 Lightweights equipped with AC Ignition and using Lucas PRS8 Switch.	TC334
1957	19-Dec-56	Identifying the Wiring on 1957 and 1958 T20 & T20C Lightweights equipped with AC Ignition and using Lucas PRS8 Switch.	TC335
1957	18-Jan-57	Instructions for Installing Triumph Racing Cams. Q Cams.	TC336
1957	21-Jan-57	Important Dimensions for Respoking Triumph Wheels. Offset Settings for all Triumph Wheels.	TC337
1957	30-Jan-57	Parts Required for fitting the Twin Carburettor "Splayed Port" Head to 1955-57 T100 and TR5 Models.	TC338
1957	04-Feb-57	Parts List for the Swinging Arm T20C Competition Models. Includes Part Numbers.	TC339
1957	21-Feb-57	Exchange Prices on Lucas Electrical Equipment. Exchange Repair Price List.	TC340
1957	13-Mar-57	Procedure for Mounting the CD85 Saddlebag Mounts and Saddlebags. Instructions	TC341
1957	25-Mar-57	Amal Carburettor Service Kit. New Larger Kit and Prices.	TC342
1957	06-May-57	Lucas and Smiths Guarantee Claims. Parts should be sent directly to the Distributors rather than Tri-Cor.	TC343

1957	04-Jun-57	Light Alloy Wheel Rims Available in Three Sizes. Part Numbers and Prices.	TC344
1957	16-Jul-57	Service Notes on 1957 Twins. Interesting Document Detailing Changes to Models during Production as a result of Customer Issues.	TC345
1957	16-Jul-57	Service Notes on 1957 Lightweight Models.	TC346
1957	31-Jul-57	Pistons fitted to TR6 and T110 Models with the Alloy Cylinder Head. From 75026 New Pistons fitted @ 8.5 to 1	TC347
1957	15-Aug-57	Exchange Prices on Lucas Electrical Equipment. New Instructions.	TC348
1957	20-Sep-57	Whitworth Spanners at Discount Prices. Price List.	TC349
1957	26-Sep-57	Price Reduction on all Triumph Decals from the Accessory Catalogue.	TC350
1957	11-Oct-57	Service Shop New Hourly Rates. New Form and Instructions. Flat Rates for Rebuilds and Reconditions.	TC351
1957	11-Nov-57	Triumph Spare Parts Retail Price List for 1958 Models. Cover Letter Only.	TC352
1957	13-Nov-57	Changes to Advertised Specification for T20/C-A and T20/C Cubs. Band Style Motif Remains on Small Tank Models.	TC353
1957	21-Nov-57	Castrol "Stick On" Labels. Castrol Warning Labels to be applied to Customers Machines.	TC354
1957	01-Dec-57	Lodge Spark Plugs. Retail and Dealer Price List.	TC355
1957	03-Dec-57	Special Instructions for Assembling the Front Forks of 1958 Twins due to the introduction of the Shouldered Fork Sleeve Nut	TC356
1957	03-Dec-57	Instructions for Installing "Tri-Cor" Flywheel Magneto on all Terrier and Cub Models.	TC357
1957	03-Dec-57	Slotted Clutch Plates T1363WT Exchange Scheme. New Parts to cure Sticking Clutch.	TC358
1957	173	T100 Splayed Port Cylinder Head. Technical Data. (Important)	843
1957	180	Twinset Recovering.	844
1957	183	Uncrating and Setting up New M/cycles.	845
1957	187	T15, T20, & T20C Sprockets, Chains & Ratios.	846
1958	10-Jan-58	Preparation and Service Notes on the new 1958 "Twenty One" Model. Battery Cover CD91	TC359
1958	13-Jan-58	Gear Ratio Sheet for Triumph Lightweights. Comprehensive Details.	TC360
1958	14-Jan-58	Control Cables Available from Stock. Part Numbers for each model and Prices.	TC361
1958	16-Jan-58	Announcing Tri-Cor Cleaning and Service Products. Hand Cleaner, Penetrating Oil, Chrome Cleaner etc.	TC362
1958	16-Jan-58	Complete List of Spokes used on all Current Triumph Models. Comprehensive List of Part Numbers and Dimensions for 1958.	TC363
1958	18-Jan-58	Swing Arm Frame Pivot Pin/Bush Removal. Description of Puller and Instructions.	TC364
1958	28-Jan-58	1958 Triumph and Tri-Cor Accessory Catalogue. Description of recommended Prices.	TC365
1958	12-Feb-58	Minimum Parts Stock for New Dealers. Initial Minimum Stock Levels for New Dealer Franchises.	TC366
1958	01-May-58	Guarantee Claims on Lucas Electrical Products. Dealers can now return Warranty parts to Tri-Cor.	TC367
1958	19-May-58	Service Notes for 1958 Models. Important Document with details for the "Twenty One".	TC368
1958	20-Jun-58	Service Notes for 1958 Lightweight Models. Important Document with details of the Racing Kit for the Tiger Cub.	TC369
1958	01-Jul-58	New CD40 Racing Valve Spring Kit for the Terrier and Cub Models. Detailed Instructions, Parts Numbers and Prices.	TC370
1958	07-Jul-58	Bolt Kit (200 Bolts) and Nut Kit with Sizes and Part Numbers. New Workshop Tools and Part Numbers.	TC371
1958	28-Jul-58	Loose Alternator Rotors on 1958 Tiger Cub Models. Remedy by New Rotor Nut, CD116	TC372

1958	22-Aug-58	Loose Alternator Rotors on 1958 Tiger Cub Models. Remedy by New Rotor Nut, CD116. Re written sheet from above.	TC373
1958	09-Sep-58	New Parts for the Tiger Cub Competition Models. Straight Exhaust Pipe and Front Fork Reinforcing Plate and Bridge.	TC374
1958	18-Sep-58	New Improved (Thicker) Push Rod Cover Seals for the "Twenty One" E3758. With fitting Instructions.	TC375
1958	29-Oct-58	Procedure for mounting CD85/21 Saddlebags to the "Twenty One". Parts required Drawing and Dimensions	TC376
1958	30-Oct-58	Procedure for mounting CD107 Saddlebags to the T20 Road Models. Parts required and Dimensions	TC377
1958	10-Dec-58	Oil Pressure Gauge for checking Oil Pressure on Twins. Not 3TA or 5TA. Includes Details.	TC380
1958	16-Dec-58	T20/S Racing Cub. Two Tone Red and Ivory Finish. Not Blue and Ivory as Advertised.	TC381
1958	195	T21 (Twenty One) Battery Carrier Modification	847
1958	196	Repair Shop By Appointment	848
1959	31-Oct-58	New Tools and Racing Parts for the T20 Model. Also 17 tooth Lay shaft Sprocket for the "Twenty One"	TC378
1959	31-Oct-58	Preparation and Service Notes for the 1959 Bonneville T120 Model. Includes Technical Details and Optional Throttle Cables.	TC379
1959	08-Jan-59	Instructions for Dismantling the T20 Engine for Repair. Full instructions and Special Tools Needed,	TC401
1959	09-Jan-59	Instructions for Setting up and Servicing a 1959 6T Thunderbird. Pre-Sale Instructions.	TC402
1959	10-Jan-58	Setting up and Service notes for the 1958 "Twenty One". Use of Plastic Battery Cover CD91 and Battery Filling Instructions.	TC403
1959	10-Jan-59	Assembly Instructions for the T20 Engine Unit. Complimentary article to 59/1. Includes Gear Ratios and Sprocket Details	TC404
1959	23-Jan-59	Service Notes on the 1959 Tiger Cub Scrambler T20S Model. With Technical Specification. Also additional Revised Data	TC405
1959	12-Feb-59	Minimum Parts Stock for New Dealers. Parts Numbers and Prices to Dealer	TC406
1959	18-Feb-59	New Parts Applicable for the T20S Tiger Cub Scrambler. Comprehensive list with Part Numbers.	TC407
1959	27-Feb-59	Conversion of a Triumph TR6A to Triumph Bonneville T120. Letter from Bill McDowell Sales Promotions Manager Tri-Cor.	TC408
1959	22-Apr-59	Instructions for Installing the Seat Rail to the 5TA. CD18 Seat rail, Instruction Sheet	TC409
1959	01-May-59	Refacing the Clutch Driving Plates on Twins and Lightweights. Clutch Sprocket for Lightweights. Goodyear Pliobond!	TC410
1959	30-Apr-59	Fitting Deluxe Saddlebags and Seat Rails to all Twins except 3TA and 5TA. CD144 Saddlebags and CD172 Mounting Brackets.	TC411
1959	26-May-59	Triumph 5TA for Class "C" Racing. Brochure Sheet showing 5TA/R for Road and Dirt Track Racing. Race Kit Available.	TC412
1959	04-Jun-59	New Tri-Cor Mark 2 Magnetos for Triumph Tiger Cubs. Three sets of Magnetos available to cover Terriers and Cubs.	TC413
1959	04-Jun-59	Installation Instructions for the Tri-Cor Mark 2 Magneto to the Terrier and Tiger Cub Models.	TC414
1959	04-Jun-59	Dealers Confidential Price List. Spare Parts for Mark 2 Magnetos for Tiger Cub.	TC415
1959	10-Jun-59	Tri-Cor Dip Cleaner. "Gunk" Available	TC416
1959	12-Jun-59	Gear Ratio Sheet for the Triumph 5TA Model. Comprehensive List.	TC417
1959	12-Jun-59	Instructions for Mounting CD144 Deluxe Saddlebags to the "Streamliner" Models using CD173 Mounting Brackets.	TC418
1959	10-Jul-59	Instructions for Installing Tri-Cor Oil Filter on Triumph Lightweights Models. Cartridge Filter Unit for Cubs!	TC419
1959	10-Jul-59	Tigress Scooter Accessories. Factory Accessories for the Tigress Scooter. Price List. Windshield and Wheel Discs Fitted as Standard.	TC420
1959	14-Jul-59	New Type Timing Pinion and Distributor Drive Gear Assembly for the Tiger Cub. E4079	TC421
1959	22-Jul-59	Setting up and Servicing the Triumph Tigress Scooter. Uncrating, Assembly and Servicing.	TC422

1959	20-Aug-59	Service Notes on the 1959 Gearbox fitted to the Big Twins T110, T120 etc. Modification to the Foot shift Lever.	TC423
1959	09-Sep-59	Instructions for fitting CD184 Float Control bracket kit to the Bonneville T120. Moving the remote Float Bowl between the carburettors.	TC424
1959	23-Sep-59	Tiger Cub Exchange Connecting Rods E3624EX and Reconditioned Timing Side Pinion Gears.	TC425
1959	30-Sep-59	New High Compression Piston for The Tiger Cub Racing Models. US made Piston.	TC426
1959	01-Oct-59	Monthly Hints and Tips from Tri-Cor Service Dept. Service Notes.	TC427
1959	01-Oct-59	Converting the Bonneville T120 from Manual to Auto Advance Ignition. Service Sheet	TC428
1959	01-Nov-59	Monthly Hints and Tips from Tri-Cor Service Dept. Service Notes. Describes a Cartridge Filter for the 1960 Twins. "Woods" Kit	TC429
1959	02-Nov-59	New "Woods" Kit for the T20S Tiger Cub. Detailed Part List for Performance Improvement.	TC430
1959	02-Nov-59	Flat Labour Rate Charges for Service Operations at Tri-Cor Service Dept.	TC431
1959	13-Nov-59	Use of Triumph Mark 3 Electrical Test Set. Instructions for Testing Lucas RM13 Equipment on Tiger Cub Models except T20S	TC432
1959	13-Nov-59	Use of Triumph Mark 3 Electrical Test Set. Instructions for Testing Lucas RM13/15 Equipment on Late model Twins	TC433
1959	13-Nov-59	Use of Triumph Mark 3 Electrical Test Set. Instructions for machines fitted with Lucas DC Equipment	TC434
1959	16-Nov-59	Air Cleaners now available for the Bonneville T120 and TR7 (TR6) models.	TC435
1959	01-Dec-59	Genuine Triumph Carton Pack Pistons Carried in Stock at Tri-Cor. Oversize's, Compression Ratios and Prices for all Pistons.	TC439
1959	14-Dec-59	Instructions for Mounting CD144 Deluxe Saddlebags to the Non "Streamliner" Swing Arm Twins using CD172 Mounting Brackets.	TC440
1959	23-Dec-59	New Push Rod Seals available for all "C" range Twins up to H7141. Fitting Instructions.	TC441
1959	Scooter	Tigress Removing the Side Valances	276
1959	Scooter	Tigress Dismantling for Decarbonising	277
1959	Scooter	Tigress Removal of Engine, Gearbox & Final Drive Nut	280
1959	Scooter	Tigress Speedometer Cable.	791
1959	Scooter	Tigress Neutral Finder.	792
1959	Scooter	Tigress Ignition Timing & Valve Clearances.	793
1959	Scooter	Tigress 250 Improvements.	794
1959	205	3TA, 5TA Oil Pipes. Petrol Tank Fixing on 650cc's, Recommended Lubricants	849
1960	17-Nov-59	New Crankshaft Bolts for 1960. New Parts for 650cc models, to be retro fitted to 1959 models in stock. Engine number 20076 on...	TC436
1960	20-Nov-59	New Crankshaft Bolts fitted as standard to machines from O 27610. Supplementary Note to 59/21	TC437
1960	01-Dec-59	Monthly Hints and Tips from Tri-Cor Service Dept. Service Notes for 1960 Models. Great Details	TC438
1960	04-Jan-60	Replacement of Flywheel Bolts. Engine Numbers O20076 to O27610 Important Warranty Issue.	TC442
1960	08-Jan-60	Fitting Instructions for the Cartridge Oil Filter for 650 cc Twins. CD174/TR7 Oil Filter. Includes Drawing.	TC443
1960	09-Jan-60	Monthly Hints and Tips from the Tri-Cor Service Department. Interesting Details on 1960 Models.	TC444
1960	12-Jan-60	Exchange Prices on Lucas Electrical Equipment. Part Numbers and Prices.	TC445
1960	22-Jan-60	Stator Guard for RM13/15 Alternator. CD194. Fitting Instructions with Drawing.	TC446
1960	01-Feb-60	Monthly Hints and Tips from the Tri-Cor Service Department. Interesting Details on 1960 Models. Essential Reading.	TC447

1960	01-Mar-60	Monthly Hints and Tips from the Tri-Cor Service Department. Interesting Details on 1960 Models. Essential Reading.	TC448
1960	01-Mar-60	Gear Ratio Chart for Triumph "B" range Twins. Comprehensive List.	TC449
1960	02-Mar-60	Important Service Notes for 1960 Tiger Cub Models. New Parts for 1960 Cubs.	TC450
1960	14-Mar-60	Exhaust Pipes and Silencers (Mufflers) fitted to all "B" Range Models from 1958 to 1960. Part Numbers for all Items.	TC451
1960	01-Apr-60	Monthly Hints and Tips from the Tri-Cor Service Department. Interesting Details on 1960 Models. Essential Reading.	TC452
1960	01-May-60	Monthly Hints and Tips from the Tri-Cor Service Department. Interesting Details on 1960 Models. Essential Reading.	TC453
1960	01-Jun-60	Monthly Hints and Tips from the Tri-Cor Service Department. Interesting Details on 1960 Models. Essential Reading.	TC454
1960	20-Jul-60	Smith's Speedometers and Tachometers Service Exchange Plan. 90 day Guarantee.	TC455
1960	20-Jul-60	Triumph Tiger Cub Instruction Manual No.7 Important Amendments to the Instruction Manual.	TC456
1960	20-Jul-60	Monthly Hints and Tips from the Tri-Cor Service Department. Interesting Details on 1960 Models. Essential Reading.	TC457
1960	20-Jul-60	Gear Ratio Chart for Triumph Lightweights. Comprehensive List updated from 1958.	TC458
1960	31-Aug-60	Instructions for installing CD213 Saddlebag Mounts to the "C" and "B" Range Twins with Rear Enclosure.	TC459
1960	01-Aug-60	Monthly Hints and Tips from the Tri-Cor Service Department. Interesting Details on 1960 Models. Essential Reading.	TC460
1960	13-Sep-60	Instructions for Installing CD231 Fork Cover Sleeves to TR6 and TR7 Models (Trophy and Bonneville)	TC461
1960	13-Sep-60	Monthly Hints and Tips from the Tri-Cor Service Department. Interesting Details on 1960 Models. Essential Reading.	TC462
1960	27-Sep-60	Twin Carburettor Balance Tube Kit. Balance Tube Kit for the Bonneville CD223. Fitting Instructions.	TC463
1960	01-Oct-60	Monthly Hints and Tips from the Tri-Cor Service Department. Interesting Details on 1960 Models. Essential Reading.	TC464
1960	08-Dec-60	"C" Range Models fitted with Energy Transfer Ignition. Service Sheet.	TC465
1960	Scooter	Tigress TW2 Waverly Accessories	231
1960	Scooter	Tigress Adjustments without Dismantling	275
1960	Scooter	Tigress Carburation	275
1960	Scooter	Tigress Changing Brake Shoes	275
1960	Scooter	Tigress Petroil Lubrication	275
1960	Scooter	Tigress Re-Assembly Engine, Gearbox & Final Drive Nut	275
1960	Scooter	Tigress Removal of Engine, Gearbox & Final Drive Nut	275
1960	Scooter	Tigress Removing & Refitting front mudguard, Legshield & Steering	275
1960	Scooter	Tigress Removing & Refitting Side Valances	275
1960	Scooter	Tigress Removing & Replacing Petrol Tank	275
1960	Scooter	Tigress Replacing Engine, Gearbox & Final Drive Nut	275
1960	Scooter	Tigress Service Tools for 175 & 250cc	275
1960	Scooter	Tigress Scooter Useful Data	275
1960	Scooter	Tigress TS1	275
1960	Scooter	Tigress Dismantling Engine, Gearbox & Final Drive Nut	778
1960	Scooter	Tigress Re-Assembly Engine, Gearbox & Final Drive Nut	779

1960	Scooter	Tigress Attention to Valves	780
1960	Scooter	Tigress Replacing Engine, Gearbox & Final Drive Nut	781
1960	Scooter	Tigress Adjustments without Dismantling	782
1960	Scooter	Tigress Removing & Refitting Front Mudguard, Legshield & Steering	783
1960	Scooter	Tigress Dismantling Front Fork & Wheel	784
1960	Scooter	Tigress Changing Brake Shoes	785
1960	Scooter	Tigress Removing & Replacing Petrol Tank	786
1960	Scooter	Tigress Changing Speedometer or Cable	787
1960	Scooter	Tigress Lucas 5AF Alternator	788
1960	Scooter	Tigress Lucas M3 Pre-Engaged Starting Motor with Roller Clutch Drive	789
1960	Scooter	Tigress Twin Coil Ignition Systems & Emergency Starting	790
1960	Scooter	Tigress Mileage Service Scheme.	795
1960	Scooter	Tigress 175cc Carburettor.	796
1960	Scooter	Tigress 250cc Carburettor.	797
1960	Scooter	Tigress 250cc Primary Drive.	798
1960	Scooter	Tigress Automotive unit Assembly Engine Mount.	799
1960	206	Special Equipment fitted to Metropolitan Police Machines. (Important)	850
1960	207	Supply of Sidecar Fork Conversion Parts	851
1960	209	T110,TR6 and T120 Electrical Equipment	852
1960	210	Energy Transfer Ignition and T100A Valve timing	853
1960	211	Wheel Building Dimensions, All Models to 1960 (Important)	855
1960	212	Service Notes, Cubs, Fork Oil Grades & Alternator Grommet.	854
1960	214	6T and T110 Camshaft and Tappet Clearances. Ramp Camshaft Mark	856
1961	09-Jan-61	Basic Instructions for the Set-Up of New Triumph Motorcycles. Uncrating and Assembly Instructions.	TC466
1961	01-Feb-61	Monthly Hints and Tips from the Tri-Cor Service Department. Interesting Details on 1961 Models. Essential Reading.	TC467
1961	07-Mar-61	Letter from John Nelson to Denis McCormack. Kit of Parts to convert Bathtub Models to Open Frame condition	TC468
1961	21-Mar-61	Minimum Parts Stock for New Dealers. Parts Numbers and Prices.	TC469
1961	14-Apr-61	Triumph Warranty Claims during 1961. Details of new parts available for 1960 models to convert to 1961 condition.	TC470
1961	26-Apr-61	Fitting CD144 Deluxe Saddlebags using CD172 Mounting Bracket to "B" Range Twins (Unstreamlined)	TC471
1961	24-Apr-61	Instructions for Installing Tri-Cor Mark 2 Magneto to 1960 to 1961 Cubs.	TC472
1961	02-Jun-61	Service Fix to Cure Wet Sumping on 1960 and 1961 Tiger Cubs. Instructions to cure.	TC473
1961	21-Jul-61	General Service Notes on the 1960 and 1961 Models. Essential Reading	TC474
1961	10-Aug-61	Electrical Problems with 1960 and 1961 650 cc Twins. New Parts and Fixing solutions for problems.	TC475

1961	19-Aug-61	Lucas Parts. Poor Warranty Service and Poor Quality Parts. Interesting document detailing development of new parts by Lucas.	TC476
1961	13-Sep-61	Tri-Cor Tubular All-Alloy Push Rods for Tiger Cub Racers. Fitting Instructions.	TC477
1961	10-Oct-61	Instructions for Installing CD220 Deluxe Seat rail. Fitting Instructions of the New Universal Seat Rail.	TC479
1961	18-Oct-61	Instructions for Timing the Ignition on E.T Equipped "C" Range Machines. Instructions.	TC480
1961	23-Oct-61	Control Cables Available from Stock. Part Numbers for each model in the range.	TC481
1961	31-Oct-61	Useful Workshop Tools. Part Numbers and Prices.	TC482
1961	24-Nov-61	Rubber Cover for the Lucas 31784 Lighting Switch. Fitting of this New Part to all models with this switch. Colours to Switch	TC483
1961	04-Dec-61	Instructions for Fitting CD144 Deluxe Saddlebags to "C" range Sports Models. TR5AR, TR5AC, T100SR and T100SC.	TC484
1961	Scooter	Tina Scooter Service Chart	278
1961	Scooter	Tigress 250cc Carburettor.	800
1961	Scooter	Tigress 175 & 250cc Electrical Equipment.	801
1961	Scooter	Tigress 250cc Tappet Settings.	802
1961	218	Tiger Cub Oil Pump and Right Main Bearing	857
1961	219	T100A Electrical and Ignition System	858
1961	221	Bonneville 120 High Speed Equipment (Thruxton)	859
1961	223	Tiger Cub push rod cover	860
1961	224	Repair Orders System for Dealers	861
1961	229	Ignition Timing on Energy Transfer Equipped Motorcycles	862
1962	01-Oct-61	New Lucas Parts for 1962 Models, Full List with Parts Numbers for each model in the Triumph Range.	TC478
1962	26-Dec-61	1962 T20 Road Cub Fitted with the New Amal 32/2 Lightweight Carburettor. Experimental Choke Control Rod.	TC485
1962	12-Jan-62	Basic Instructions for Uncrating Setting Up and Servicing 1962 T100SR and T100SC.	TC501
1962	12-Jan-62	Instructions for Overhauling Triumph Tiger Cub Engines. Full Instructions.	TC502
1962	13-Jan-62	Part CD108 Spindle Puller. Instructions for Use on all Triumph Swing Arm Models.	TC503
1962	23-Feb-62	Hints and Tips for 1962 Models.	TC504
1962	21-Mar-62	Gear Ratios for "B" Range Twins. Covering all B range Models from 1959 to 1962. Very Interesting Information.	TC505
1962	04-Apr-62	Amendments to Specifications for 1962 Cub, Bonneville and TR6SR. Interesting Document.	TC506
1962	26-Apr-62	Important Service Notes for 1962 Models. Incorrect Main Jets in T120, Oil Tank Bolts, New Stop lamp Switch	TC507
1962	03-May-62	Important Notes on Warranty Claims. New Tool for Timing Side Bearing on "C" Range Machines.	TC508
1962	03-May-62	Improved Stoplight Switch. Fitting to Shock Absorber Bolt and Brake Rod.	TC509
1962	10-May-62	Special Sale of Certain Tri-Cor Products. Polish, Hand Cleaner, Penetrating Oil.	TC510
1962	25-May-62	Transmission Gears Available for Triumph Models 1950 to 1962. Gear Teeth and Part Numbers for All Gearboxes and Models.	TC511
1962	25-May-62	New Items Available. New Tools and US made Pistons for 500 cc Twins and Cubs. Finned Rocker Caps, Valve Springs.	TC512
1962	02-Jul-62	Service Notes for the 1962 Triumph Models. New Ammeter, Brake Light Switch, Clutch Plates	TC513

1962	15-Aug-62	Basic Notes on Preparation of Triumph Motorcycles for the Jack Pine Enduro. Interesting Document.	TC514
1962	17-Aug-62	New Balance Factor for 650cc Crankshaft Assembly. Part Numbers for the crankshaft assemblies for Engines before D15788	TC515
1962	27-Aug-62	Lucas Switch Kit to Convert 1960 B range Twins to the 1962 Sealed Switch Specification.	TC516
1962	31-Aug-62	Kit of Racing Valve Springs for Tiger Cub Models. Part Numbers and Prices.	TC517
1962	30-Oct-62	Introduction of Silicone Bridge Rectifiers 2DS506 on 1963 TR6 and T120 Motorcycles.	TC518
1962	03-Dec-62	Gear Ratio Chart for Triumph "B" Range Unit Construction Twins. Includes 1963 Models	TC519
1962	13-Dec-62	Lucas Stators and Rotors Fitted to Triumph Motorcycles from 1954 to 1962. Lucas Part Numbers for all Models	TC520
1962	17-Dec-62	Universal US made Condenser for all Triumph Models with Fitting instructions.	TC521
1962	Scooter	Colours	147
1962	Scooter	Tina Scooter Service Chart	493
1962	Scooter	Tigress Service Scheme.	803
1962	Scooter	Tina Hard Starting	813
1962	Scooter	Tina Service Tools	814
1962	Scooter	Tina Parking Light Fitting	815
1962	Scooter	Tina Transmission Belt	816
1962	Scooter	Tina Transmission. New Parts	818
1962	230	Amal Type 32 Carburettor Spares List Illustrated	863
1962	232	Police Users. Clutch Cables, Clutches and H/duty Centre Stands	864
1962	233	650cc Twin Crankshaft Assembly. Alterations with Part Numbers	865
1962	236	Workshop & Service Exchange Unit Charges	866
1962	237	Lucas Rectifiers. Fitting of the New Miniature Lucas Rectifier From D18419	867
1962	238	T20 SH Charging Rate	868
1963	19-Dec-62	Wiring Colours and Connections for the 1963 "A" Range. Applies only to the 1963 T20 Road Model. With Battery and Points Ignition.	TC522
1963	20-Dec-62	Wiring Colours and Connections for the 1963 "B" Range. Applies only to the 1963 Models. With twin Points and Dual Coil Ignition.	TC523
1963	19-Dec-62	Wiring Colours and Connections for the 1963 "C" Range. Applies only to the 1963 T100SR Models. With twin Points and Dual Coils	TC524
1963	20-Dec-62	Service Notes for the 1963 "C" Range T100SR Model. Interesting Document.	TC525
1963	07-Jan-63	Use of Mark 3 Electrical Test Set for testing the Lucas RM19 Equipment on the "B" and "C" Range Twins	TC526
1963	07-Jan-63	Use of Mark 3 Electrical Test Set for testing the Lucas RM18 Equipment fitted to the 1962 and 1963 T20 Road Cub Models.	TC527
1963	18-Jan-63	Triumph Warranty Claims. Replacement Frames for 1960 "B" Range Models and Flywheel Bolts on 1960 "B" and "C" Models.	TC528
1963	23-Jan-63	Instructions for Fitting CD172/CS63 Saddlebag Mounting Kits to the T100SR Model.	TC529
1963	23-Jan-63	Instructions for Fitting CD172/B63 Saddlebag Mounting Kits to the 1963 T120R and TR6R Models.	TC530
1963	23-Jan-63	Minimum Parts Stock for New Dealers. Parts and Price List.	TC531
1963	04-Feb-63	Genuine Triumph Carton Pack Pistons in Stock at Tri-Cor. Part Numbers for all pistons.	TC532

1963	15-Feb-63	New Items, Parts and Accessories for the Spring Sales Season. Includes Handlebar Styles (5 Types) and Dimensions.	TC533
1963	14-May-63	Gear Ratio Chart for Triumph "B" Range Unit Construction Twins. Includes 1963 Models	TC5192
1963	15-May-63	Information for those Dealers who have received a 1963 T120 "TT Special" Model. Important Document	TC534
1963	18-Jun-63	Special B for All Eastern Triumph Dealers who have received 1963 "B" Range Models before 14th June 1963. Oil Line Failures.	TC535
1963	03-Jul-63	Exchange Prices on Lucas Electrical Equipment. All models 1954 to 1963.	TC536
1963	15-Jul-63	Lucas Stators and Rotors Fitted to Triumph Motorcycles 1954 to 1963. All Models.	TC537
1963	09-Oct-63	Bell Safety Helmet Repair Service.	TC538
1963	23-Oct-63	New Tools for Removing and Replacing 1963 Exhaust Camshaft on 1963 Models.	TC539
1963	22-Nov-63	New Improved Alloy Valve Collars and Steel Collets. Old Valve Collars to be Scrapped.	TC540
1963	25-Feb-63	1963 "B" Range Twin Models. Service Issues	TC541
1963	24-Apr-63	1963 "B" Range Twin Models. Service Issues. New Factory Handlebars and other details	TC542
1963	19-Jul-63	New Improved Parts Available to fit 1963 T120 and TR6 Models. New Crankcase Filter, HD Clutch Springs, Reinforced Switch Panel, Clutch.	TC543
1963	27-May-63	1963 "C" Range 500cc Models. General Details and Supplementary Parts List.	TC545
1963	20-Mar-63	Important Service Tips for the T20SR and T20SC Models. Stop Light Failures.	TC546
1963	03-May-63	Special Parts for converting a Tiger Cub to 250cc Displacement. Suitable for engines after 57616	TC547
1963	Scooter	Tina Steering Head. New Parts for 1963	817
1963	Scooter	Tina Front & Rear Brakes	819
1963	Scooter	Tina Hard Starting	820
1963	Scooter	Tina Transmission	821
1963	Scooter	Tina Rear Driven Pulley	822
1963	Scooter	Tina Kickstart	823
1963	241	Tiger Cub Crankshaft. New Parts Apply	869
1963	243	Speedometer Drive Ratios for 1963 650cc Twins	870
1963	251	"C" Range All Models Gear Ratios	873
1964	08-Nov-63	Service Notes for the New 1964 Models. Important Document covering detail changes over the 1963 Models.	TC544
1964	17-Jan-64	Basic Instructions for Setting Up New 1964 Triumph Twins.	TC548
1964	17-Jan-64	Use of Mark 3 Electrical Test Set for testing the Lucas RM19 Equipment on the 1963 and 1964 "B" and "C" Range Twins	TC549
1964	04-Feb-64	New Workshop Tools for the 1964 Models. Price List	TC550
1964	19-Feb-64	How to use the new CD385 "Top Centre" Tool and Ignition Timing Kit.	TC551
1964	30-Oct-64	Wheel Building Dimensions for all Models. Useful Data Sheet	TC552
1964	16-Nov-64	Minimum Parts Stock for New Dealers. Part Numbers and Prices	TC553
1964	17-Jan-64	Wiring Colours for the 1963 and 1964 "B" Range Twin Models with 6V Lighting and Twin Contacts and Coils	TC554
1964	06-Mar-64	Service Notes on the 1964 "B" Range Twins. Includes Details on the "Q" or "TT" Camshaft.	TC555

1964	01-Jun-64	Important Corrections for 650 cc "B" range Parts Book #2. You Must Read This!	TC556
1964	18-Jun-64	Important Service Notes for Sales and Service Personnel.	TC557
1964	01-Sep-64	Replacement parts for the Dual Twist grip as fitted to the T120R and T120TT Special.	TC558
1964	09-Nov-64	Information for Dealers who have received a 1965 T120 "TT Special" Model.	TC559
1964	17-Jan-64	Wiring Colours for the 1963 and 1964 "C" Range Twin Models with Twin Contacts and Coils. T100S/R	TC560
1964	08-Jul-64	Replacement Parts Catalogue #5 for the 1964 "C" Range Twins. Important Revisions. Vital Document for US Restorers.	TC561
1964	05-Mar-64	Important Service Information for all Tiger Cub Engines produced from #84269 to #97200. Sludge Trap Issues under Warranty.	TC562
1964	245	Ignition Timing Figures for All Models.	871
1964	250	650 unit twin Pre-sized Swinging Arm Bushes	872
1964	254	Tina Scooter Spares & Service Arrangements	876
1964	255	Tina Scooter Service Arrangements	877
1964	256	Tina Scooter Important Adjustments	878
1964	257	All Models Owners Handbooks in Spanish and French	879
1964	258	Guarantee Claims - Proprietary Components	880
1964	259	5TA. Parts Required when Preparing Engines for High Performance.	881
1965	07-Jan-65	Suggested Flat Rate Labour Charges for Service Operations.	TC601
1965	14-Jan-65	Lucas Stators and Rotors fitted to Triumph Motorcycles. 1954 to 1965. All Models	TC602
1965	18-Jan-65	1964 Type Fork Springs fitted to "B" and "C" Range Twins. Optional Springs and Collars from Tri-Cor.	TC603
1965	22-Feb-65	The VDO Enduro Speedometer. Fitting Instructions with Illustration and Tools Required	TC604
1965	01-Apr-65	New Parts and Accessories. Includes details of Glass Fibre Tanks for 650's and new tools.	TC605
1965	04-May-65	Use of Triumph Electrical Test Set Model 102. Instructions for Testing the Lucas RM19 Equipment on 6V Machines	TC606
1965	11-May-65	Luggage Rack and Seat Rail Combination. Saddlebag Brackets.	TC607
1965	07-Jul-65	Float Bowl Gauge for Carburettor	TC608
1965	15-Jul-65	New Ignition Timing Disc, Improved Plastic.	TC609
1965	23-Jul-65	Important Service Notes for 1965. Chain Oiler on Late 65 Models and Ammeter Problems.	TC610
1965	03-Aug-65	Rear Wheel Bearing Failures on 65 "B" Range Models. Felt Seal requires Oiling before assembly.	TC611
1965	18-Aug-65	Wisco Battery Alternative to Lucas MLZ9E Battery.	TC612
1965	08-Sep-65	New Protective Carburettor Covers for Monoblock Carburettors.	TC613
1965	28-Sep-65	New Prices on Lucas Batteries for all Triumph Models.	TC614
1965	07-Oct-65	Lucas Stators and Rotors fitted to Triumph Motorcycles. 1954 to 1966. All Models.	TC615
1965	08-Oct-65	Exchange Prices on Lucas Electrical Equipment.	TC616
1965	12-Oct-65	Model 102 Electrical Test Set Instructions for Early Models with DC Generators and Regulators.	TC617
1965	12-Oct-65	Model 102 Electrical Test Set Instructions for RM18 Equipment as fitted to 1962-1965 Battery Ignition T20 Road Cub Models.	TC618

1965	10-Nov-65	Jomo Valve Springs for 650cc Models Prior to 1966. Instructions.	TC619
1965	09-Nov-65	Model 102 Lucas Testing Equipment for 1966 12 Volt Models. Instructions.	TC620
1965	10-Dec-65	Countershaft (Gearbox) Sprockets for All Models.1946 to 1966.	TC621
1965	08-Dec-65	Rear Wheel Sprockets and Bolt Over Sprockets for All Models.	TC622
1965	08-Dec-65	Chain Oiler on Late 65 Twins and Early Production 1966 Models. Up to DU27893 and H41567.	TC623
1965	11-May-65	Service Notes on 1965 "B" Range Twins.	TC624
1965	260	650cc Twin Rear Wheel Bearings	882
1965	261	All Models Damage In Transit	883
1965	262	Stroboscope Kit - CP 207 Assembly & Use	884
1965	264	Motorcycles Returned to Factory use of Factory Contract Transport.	885
1965	265	650cc Exhaust Camshaft Oiling - Fitting Instructions Pre DU 24875	886
1966	06-Oct-65	Information for Dealers who have received a 1966 T120 "TT Special" Model.	TC625
1966	08-Dec-65	Service Notes on 1966 "B" Range Twins.	TC626
1966	24-Jan-66	Oil Bleed Holes in Connecting Rods leading to issues with "B" Range Twins. Covers engines DU19895 to DU25377 and H38904 to H41369	TC627
1966	25-Jan-66	New Tacho Drive Gearbox Recommendations.	TC628
1966	16-May-66	Jomo Valve Spring Fitting guides for pre 66 "B" Range Twins.	TC629
1966	01-Jul-66	Electrical Problems. 1966 Models with Lucas Ignition Switch. Lucar Terminals loose in switch body. Includes Wiring Diagram for 1966 Models	TC630
1966	05-Aug-66	Headlamp Bulb Failure and Rubber Mounting Kit	TC631
1966	14-Dec-66	Instructions for mounting the CD472 Seat Rail for 1967 "B" and "C" Range Models.	TC632
1966	10-Jan-66	Important Corrections to Parts Book #4 for the "B" Range Twins. Details of Part Numbers, Additions and Omissions to US Models.	TC633
1966	29-Jan-66	Service Notes for the "B" Range Twins. Variations in Kill Buttons. Exhaust Tappet Lubrication. Dunlop K70 Tyres	TC634
1966	30-Mar-66	Important Service Notes on the Latest Production Twins. General Details for Twins.	TC635
1966		1966 "B" & "C" Range Mid-Year Modifications. Important	JO100
1966	22-Apr-66	Latest Production Triumph T120R Models. Improvements from Engine/Frame DU27007 to DU34086	TC636
1966	13-May-66	Headlamp Bulb and Zener Diode Failures. Improved Heat Sink Introduced from DU30800	TC637
1966	19-Jul-66	Seat Cover Acid Damage to Early Production Models. Defective Exhaust Pipe Adaptors.	TC638
1966	08-Aug-66	Tri-Cor Cylinder Head repair tool to replace Alloy Exhaust Adaptors.	TC639
1966	03-Oct-66	Head Light Bulb and Gearbox Problems. Incorrect Camplate replaced.	TC640
1966	28-Nov-66	Information for Dealers who have received a 1967 T120 "TT Special" Model.	TC641
1966	10-Jan-66	Important Corrections to Parts Book #7 for the "C" Range Twins. Details of Part Numbers, Additions and Omissions for US	TC642
1966	10-Jan-66	Change to Gas tank Specification for US T100R and T100C	TC643
1966	10-Jun-66	Parts Tools and Accessories	TC644
1966	10-Jun-66	Fast Moving Shop Tools	TC645

1966	14-Jun-66	Pistons in stock at Tri-Cor. Pistons for all Models.	TC646
1966	14-Jun-66	Rear Wheel Alloy Sprockets for all Models.	TC6462
1966	20-Jun-66	Price Alterations and Additions for Spares	TC647
1966	22-Aug-66	Price Alterations and Additions for Spares	TC648
1966	23-Aug-66	New Prices for AMAL Spares.	TC649
1966	12-Sep-66	Revised Prices for Lucas Parts	TC650
1966	251	"C" Range All Models Gear Ratios Revised	874
1966	266	Tiger Cub Push Rod Assembly	887
1966	269	650cc Crankshaft Oil Feed Seal Recommendations	888
1966	270	Tiger Cub Cylinder Head	889
1966	271	T10 Scooter Transmission Belt	890
1966	274	650cc Exhaust Pipe Adaptors. Replace Alloy Adaptors with Steel	891
1966	275	T20 Sports Alternator Communionisation	892
1966	276	Zener Diodes and Auto-Advance Issues - 12 volt twins B858(DU30600 & H43716)	893
1967	20-Nov-66	New Parts and Accessories. Saddlebags, Seat Rails	TC651
1967	15-Dec-66	1967 "B" Range Parts Book and Price List due to be posted.	TC652
1967	01-Jan-67	Suggested Flat Rate Labour Time Schedule for Unit Construction Motorcycles.	TC653
1967	07-Apr-67	Loose Pivot Bolt on Swinging Arm and Wet Sumping 1966 and early 1967 "B" Range Models.	TC654
1967	07-Apr-67	Ignition Troubles with 1967 Twins due to Incorrect Ignition Cam Dwell Timing	TC655
1967	03-May-67	Introduction of Amal 900 Series "Concentric" Carb. Initially only on Bonneville T120R	TC656
1967	04-May-67	Gear Ratio Chart for Unit Construction "B" Range Twins. All Models.	TC657
1967	24-Aug-67	Revised Internal Connections and Test Procedure for 47197 Stator. Fitted to 1967 T120TT, TR6C, T100C and T20M	TC658
1967	24-Aug-67	Wet Sumping. Identifying and Correcting,	TC659
1967	24-Aug-67	Exhaust Tappet Lubrication System for 650cc Twins. Two Systems after DU24875 and DU63043	TC660
1967	18-Sep-67	Comprehensive Test and Troubleshooting Instructions for all Battery Ignition "B" and "C" Range Models using Lucas RM19.	TC661
1967	21-Sep-67	Tachometer Drive Thimble Replacement. Method.	TC662
1967	21-Sep-67	Change in Thread form from Cycle to Unified for Swing Arm Bolt and Gearbox Mainshaft.	TC663
1967	22-Sep-67	Fork Bushings in Late Model Twins. Replace Sintered Iron Bushes with Bronze Bushings. Testing for Wear.	TC664
1967	22-Sep-67	Unified Thread Change over. Thread Size Comparison Chart	TC665
1967	27-Sep-67	Gear Ratio Chart for Unit Construction "C" Range Twins. All Models from H5485 1959.	TC666
1967	23-Oct-67	Principles of AC (E.T.) Ignition and Lighting Systems fitted to all models from 1950. Test Procedures.	TC667
1967	21-Nov-67	Removal of the Roller Bearing fitted to the drive side of "B" Range engines from DU24875.	TC668
1967	26-May-67	Assembly Instructions for Flexibly Mounted Handlebars on "B" Range Twins from DU59320	TC669

1967	26-Sep-67	Service Notes on 1963 to 1967 "B" and "C" Range Models	TC670
1967	15-Nov-67	Service Hints and Tips for 1968 Twins. General Details	TC671
1967	18-Dec-67	Service Hints and Tips for 1968 Twins. General Details	TC672
1967	13-Feb-67	Special Parts to Convert the Tiger Cub to 250cc Displacement.	TC673
1967	26-Apr-67	Important Service Information for 1967 T20M Tiger Cub Models. New Information for 67 Models.	TC674
1967	01-Jun-67	Racing Valve Spring Kit for the Tiger Cub models. Instructions.	TC675
1967	05-Jan-67	US made Zener Diode Available	TC676
1967	24-Jan-67	Important Corrections to Parts Book #5 for the "B" Range Twins. Details of Part Numbers, Corrections and Omissions for USA.	TC677
1967	06-Feb-67	New Tools available for Service operations.	TC678
1967	10-Aug-67	Lucas Stators and Rotors fitted to Triumph Motorcycles 1954 to 1967.	TC679
1967	03-Feb-67	Lucas Stators and Rotors fitted to Triumph Motorcycles 1954 to 1967.	TC680
1967	20-Feb-67	Important Corrections to Parts Book #8 for the "C" Range Twins. Details of Part Numbers, Corrections and Omissions for USA.	TC681
1967	24-Feb-67	Corrections to Parts Book #8 for the 1967 "C" Range Models. Important Document.	TC682
1967	20-Apr-67	Mounting Instructions for the CD464 Combination Luggage Rack/Seat Rail to 1967 "B" and "C" Range Machines.	TC683
1967	20-Apr-67	Mounting Instructions for the CD469 Combination Luggage Rack/Seat Rail to 1967 "B" and "C" Range Machines.	TC684
1967	19-Jun-67	CD466B and CD466C Lower Saddlebag Mounts for "B" and "C" Range Machines.	TC685
1967	27-Jun-67	New Suggested Retail Price List Release, Effective June 1st 1967.	TC686
1967	12-Jun-67	Unified Threads. Useful Identification sheet of all Unified Thread Parts for 1966 and 1967 Twins.	TC687
1967	01-Aug-67	Changes to the Parts Book #1 for the "A" range 1966-67. New Lay shaft Low Gear.	TC688
1967	02-Aug-67	Bell Helmets, Helmet Specifications and States with a Compulsory Helmet Law	TC689
1967	03-Aug-67	Dunleer Helmet Lock. Includes Brochure Sheet.	TC690
1967	04-Aug-67	Supplement for Parts Catalogue #5 for 1967 "B" Range Models	TC691
1967	07-Aug-67	Tri-Cor Accessory Brochure Available and Recently Advertised in the Press	TC692
1967	10-Aug-67	New Tools available for Service operations.	TC693
1967	10-Aug-67	Pistons in Stock at Tri-Cor. Comprehensive List.	TC694
1967	06-Sep-67	New Crankshaft Locating Tool for "C" Range Engines from H50000	TC695
1967	15-Sep-67	Exchange Prices on Lucas Electrical Equipment. Part Numbers and Models.	TC696
1967	26-Sep-67	Six Month Lucas Battery Guarantee.	TC697
1967	21-Nov-67	CD522 Engine Stand. Description of the engine stand and its use.	TC699
1967	Scooter	T10 Scooter Workshop Manual Available. Publicity Sheet.	767
1967	Scooter	T10 Workshop Manual Available. Press Release	901
1967	277	T10 Scooter Petrol Tap	894
1967	278	T20B & Super Cub Electrical system - Wipac alternators	895
1967	279	Battery Vent and Drain Tube. Replacing the Battery instructions	896

1967	281	Modified 'B' All Models Timing Cover Bush in Pre 1963 Engines	897
1967	282	Bantam/Super Cub - Additional part numbers	898
1967	283	"B" Range Models Pressure lubrication of Exhaust Cam Followers DU24875	899
1967	284	Conversion of Tina Scooter Automatic Drive to T10 Condition	900
1967	285	650cc machines - Plug Specification Change	902
1967	286	Modified 'B' All Models Timing Cover Bush in Pre 1963 Engines	903
1967	287	Lucas 6CA Contact Breaker - Conversion from 4CA	904
1967	288	Utilisation of 1968 Finned Heat Sink on Pre-68 Twins. Zener Diode	905
1968	01-Nov-67	1968 Models. Ordering Parts before release of the Parts Books	TC698
1968	24-Jan-68	Fitting the Lucas 2MC Capacitor to Triumph Motorcycles. Allows Battery less Condition. Includes Lucas Sheet	TC702
1968	25-Jan-68	Use of CD456 Timing Kit and CD491 Crankshaft Tool to Obtain Ignition Timing.	TC703
1968	19-Feb-68	C' Range Pistons Oversize Sizes and Rebore Specifications	TC704
1968	27-Mar-68	Camshaft Timing Triumph Engines. Comprehensive Article with Diagrams.	TC705
1968	08-Apr-68	Gearbox Ration for 500 and 650 cc Triumphs. Diagrams and Part Numbers for all Gearboxes.	TC706
1968	08-Apr-68	1968 650cc 'B' Range Crankshafts/Flywheel Condition. Variations for 1968 Models. Important Document.	TC707
1968	08-Apr-68	Flywheel Stop Pin Tool. New Tool for 1968 Crankshaft Versions.	TC708
1968	11-Apr-68	Fitting Replacement Seat Covers.	TC709
1968	15-Apr-68	Strengthened Connecting Rods on 500cc and 650cc Engines.	TC710
1968	24-May-68	Triumph Wheel Spoking, Comprehensive details on Spoke Sizes and Lengths, Rims and Wheel Offsets for All Models from 1960.	TC711
1968	27-Jun-68	Suggested Labour Charges for Service Operations on the new Trophy Model.	TC712
1968	03-Jul-68	Loose Cylinder Sleeves on TR25W Trophy Model. Rectification.	TC713
1968	03-Jul-68	T100R Daytona, Poor Idle Condition. Re-Time/Set the Points to 5 Degree Advance.	TC714
1968	03-Jul-68	Timing Plate for 'B' and 'C' range Machines with Inspection Cover in the Primary Chain case.	TC715
1968	16-Oct-68	TR25W Gearbox Problems. New Camplate and Mainshaft Selector Fork.	TC716
1968	27-Mar-68	Electrical Problems with 1963-64 Twins, Gearbox Issues and Pushrod Seals.	TC717
1968	14-May-68	Service Hints and Tips for 1968 Models. Interesting General Notes.	TC718
1968	05-Jun-58	Service Notes on 1968 TR25W 250cc Trophy Model. Gear Ratios and Carb Jet Changes.	TC719
1968	10-May-68	Preparing a Triumph TR25W for Short Track or Dirt Track Racing. Comprehensive Details.	TC720
1968	31-Jul-68	Service Notes on 1968 TR25W 250cc Trophy Model. Chain Lubrication, Side Stand.	TC721
1968	27-Sep-68	Service Notes on 1968 TR25W 250cc Trophy Model. Sump Filter Poor Soldering and Sealing.	TC722
1968	27-Sep-68	Service Notes on 1968 TR25W 250cc Trophy Model. Tappets, Fuel Tank Leaks, Oil Feed 'O' Ring.	TC723
1968	16-Oct-68	Service Notes on 1968 TR25W 250cc Trophy Model. Rear Brake Rod, Cylinder Head Gasket, Oil Leaks.	TC724
1968	25-Jan-68	New Tools for 1968 Models. Contact Breaker Puller and Crankshaft Locating Tool.	TC725

1968	02-Feb-68	Part Number Changes for Unified Nuts and Bolts. For 1966 to 1968 Models.	TC726
1968	12-Feb-68	T20 Roller Bearing Big Ends, Luggage Accessories, Dual Leading Shoe Brake For Cubs.	TC727
1968	01-Mar-68	New Triumph Service Tools. Stanchion Removal and Replacement Tool.	TC728
1968	04-Mar-68	Replacement Parts Catalogue No: 6 for the 'B' Range Models. Corrections and Additions.	TC729
1968	04-Mar-68	Replacement Parts Catalogue No: 9 for the 'C' Range Models. Corrections and Additions.	TC730
1968	06-Mar-68	New Parts Books and Printed Price Lists.	TC731
1968	26-Mar-68	Race Parts for Twins, Rigid Rear Sections for 'C' Range Machines, Helmets, Stands, Handbooks.	TC732
1968	26-Mar-68	New Lubrication System Test Set.	TC733
1968	27-Mar-68	Camshafts Available from Tri-Cor for All Twins. Part Numbers and Specifications for all Twins from 1959. (Vital for Builders).	TC734
1968	09-Apr-68	Castrol Oils, Introduction of Gran Prix Racing Oil. Price List.	TC735
1968	18-Apr-68	Replacement Parts Catalogue Corrections for Catalogue No: 6 'B' Range Models and Catalogue No: 9 'C' Range Models.	TC736
1968	26-Apr-68	Lucas Stators and Rotors Fitted to Triumph Motorcycles from 1954 to 1968.	TC737
1968	25-Apr-68	Exchange Prices on Lucas Electrical Equipment.	TC738
1968	25-Apr-68	Pistons in stock at Tri-Cor. Pistons for all Models.	TC739
1968	17-May-68	Factory Seat rails Fitted as Standard to Tri-Cor Models. Limited supplies mean some machines are not fitted but parts forwarded later.	TC740
1968	27-Jun-68	Mid-Season offers on Overstocked Parts. Parts and Prices.	TC741
1968	25-Jul-68	Replacement Parts Catalogue Corrections for TR25W 250cc Model.	TC742
1968	06-Aug-68	Additional Corrections to the TR25W Parts Book.	TC743
1968	15-Aug-68	Back Orders Computerised. High Levels of Orders being Processed.	TC744
1968	29-Aug-68	Pistons in stock at Tri-Cor. Pistons for all Models.	TC745
1968	29-Aug-68	Improved American Made Gaskets for the TR25W and Twins.	TC746
1968	19-Sep-68	Close Out, End of Line Bargains on Dunlop K70 Tires 225x17 Size.	TC747
1968	26-Sep-68	Elimination of the Lucas Exchange Program on Stators and Rotors.	TC748
1968	26-Sep-68	Lucas Electrical Parts Price Changes and Updated Price List.	TC749
1968	26-Sep-68	Bell Star and Shorty Helmets. New larger Helmet Sizes soon to be Manufactured.	TC750
1968	21-Oct-68	Replacement Parts Catalogue for the 1969 Trident 750, Important Corrections and Additions.	TC751
1968	22-Oct-68	Replacement Parts Catalogue for the 1969 'B' Range 650cc Models, Important Corrections and Additions.	TC752
1968	24-Oct-68	Replacement Parts Catalogue for the 1969 'C' Range 500cc Models, Important Corrections and Additions.	TC753
1968	13-Nov-68	New Bell Helmets available from Tri-Cor.	TC754
1968	13-Nov-68	Current back orders at Tri-Cor.	TC755
1968	14-Nov-68	Replacement Parts Catalogue for the 1969 'B' Range 650cc Models, Additional Important Corrections and Additions.	TC756
1968	16-Dec-68	Whitworth and Unified Threaded Parts used in 1968 and 1969 'B' and 'C' Range Models. Part Numbers.	TC757
1968	16-Dec-68	Gasket Set Part Numbers for All Models.	TC758
1968	27-Dec-68	Fitting of Crash Bars (Safety Bars) CD216/63 to the 1969 T120R with Dual Horns.	TC759

1968	289	Service Replacement Unit Scheme	906
1968	290	Return to the Factory of Motorcycles for Warranty Attention	907
1968	292	Using Stroboscopic Timing Plate no. D2014	908
1968	293	650cc Plug Oilways on Crankcase Assembly on pre DU 24875 Engines	909
1968	294	650cc "B" Range All Models Crankcase Flywheel Location	910
1968	295	Workshop and Service Exchange Unit Charges all Models	911
1968	296	New Cylinder Head Bolt Torque Rates for "B" & "C" Range Models	912
1968	297	Dealer Access to Repair Service	913
1968	298	Cable Run on Twin Leading Shoe Front Brake	914
1968	299	Conversion of 'Z' tools 45' & Blending Cutters to New Numbers	915
1968	301	Approved Lubricants. Mobil/Castrol/Duckhams etc.	917
1968	302	Tool Box / Left Panel Retention Clip on 1968 'Models	918
1968	303	Use of Rust Inhibiting Oil in 1969 'B' & 'C' All Models. Oil Grades	919
1968	304	UNF and UNC Threaded Components. Part Numbers	920
1968	305	650cc Increased Sump Capacity and Modification for Older Models	921
1968	307	T150 Air Control Cable Guide Bracket B 307	552
1968	310	Camshafts. Identification, Type and Usage. (Important)	923
1968	Jo-Mo	Amal Concentric Fitted to 1968 TR6C & TR6R. Needle Jet Change	1037
1968	Jo-Mo 18-	All Models Loose Ground Connection for Condensers	1044
1968	Jo-Mo 20-	TR25W Modifications for Competition	1045
1968	Jo-Mo 21-	T100R Correct Cam Timing for Twin Carburettor Models	1046
1968	Jo-Mo 28-	High Tension Racing Valve Springs	1047
1968	Jo-Mo 4-	Fork Tool Adapter No JT-1, Unified Threads All	1038
1968	Jo-Mo 6-	Unified Thread Changeover to All Models	1039
1968	Jo-Mo 7-	1968 T100R Carburettor Modifications	1040
1968	Jo-Mo 8-	Service Tips for Amal Concentric Carburettors	1041
1968	Jo-Mo 9-	Ignition Breaker Cam Run Out, 1968 "B" and "C" Range Models	1042
1968	Jo-Mo 9-	Spark Plug Cross Reference Chart	1043
1969	18-Feb-69	T150 Air Slide Control Cable Bracket. New Part.	TC760
1969	20-Feb-69	New Parts for Amal Carburettors fitted to all 1969 Models.	TC761
1969	20-Feb-69	Concentric Carburettor Choke Modification for All Models prior to DU85346 and H65573	TC762
1969	20-Feb-69	Amal Concentric Carburettor Pilot Jet Cleaning Tools.	TC763
1969	24-Feb-69	Triumph Dirt Track Racer for 1969. New AMA Rules allow 650cc Machines. Rigid Rear Frame, Disc Brake.	TC764

1969	14-Mar-69	Triumph T120 Bonneville Tank Changes. New Paint Profile.	TC765
1969	24-Mar-69	T150 Trident. Important Correction to Clutch Shock Absorber Sprocket Assembly.	TC766
1969	24-Mar-69	750cc Engine Shock Absorber Rubbers. Change of Parts in Clutch.	TC767
1969	08-Apr-69	Service Hints and Tips for the 1969 Triumph Twins. Useful Document.	TC768
1969	07-May-69	2BA Size Tap to Clean Threads on Clutch Shock Absorber. B 24/3	TC769
1969	09-May-69	Toolbox Knob Retaining Clip Now Fitted. Parts available for all earlier Models	TC770
1969	12-May-69	Jomo Valve Springs, Fitting Instructions and Part Numbers.	TC771
1969	14-May-69	New Tapered Oil Pressure Switch Thread. Do not Fit To Twins.	TC772
1969	18-May-69	Fork Stanchion Modification. New Stanchions with revised damping control holes.	TC773
1969	23-May-69	Gear Ratio Chart for the T150 Trident Model.	TC774
1969	23-May-69	1969 Triumph Fork. New Fork Dimensions applicable to All Twins and T150 Three, Parts not Interchangeable with Earlier Models.	TC775
1969	27-Jun-69	1969 500cc Triumph Twin Models up to EC17978 Engine Noise. Undersized Drive Side Bearing.	TC776
1969	03-Jul-69	Oil Leaks at Push Rod Cover Tubes on 1969 Twins. Recommendations.	TC777
1969	10-Jul-69	Wet Sumping on Twins. How to Test for Wet Sumping, Rectification. Useful Article.	TC778
1969	10-Jul-69	Tachometer Drive Thimble Replacement. Tool and Method.	TC779
1969	18-Jul-69	Oil Leaks T150 Model. Rectification Details and Service Details.	TC780
1969	15-Aug-69	TR25W Valve Collars and Taper Locks (Collets). New Replacement Parts.	TC781
1969	15-Aug-69	Service Hints and Tips for the 1969 Triumph Twins. Useful Document. Oil Leaks, Clutch Release Rod, and new Gaskets.	TC782
1969	08-Sep-69	A.C. Ignition and Lighting System on Twins 1963 to 1967. Description Article and Testing Procedures.	TC783
1969	17-Dec-69	Carburettor Main Jet Screen, Loose Jets. Incorrect Jets on 1970 T100R and T Models.	TC784
1969	23-Dec-69	Overcoming Oil Leaks at Push Rod Cover Tubes on 1969 Twins. Service Article.	TC785
1969	21-Feb-69	B Colours Revised, Green Overhaul Manual for the Triples.	TC786
1969	15-May-69	Service Notes on T150 Triple Model. Oil System, Breathing, Oil Filter Cartridge.	TC787
1969	09-Jan-69	Revised Parts Price List.	TC788
1969	09-Jan-69	Additional Corrections for the T150 Parts Catalogue. Important Additions and Corrections.	TC789
1969	10-Jan-69	Maintenance notes for the Trident 750cc Three Cylinder Model T150.	TC790
1969	10-Jan-69	Triumph T150 Five Speed Gear Assembly. Part Numbers to convert Four Speed to Five Speed Gearbox.	TC791
1969	10-Jan-69	New Prices for Spokes. Part Numbers and Prices.	TC792
1969	21-Jan-69	Minimum Parts Stocks Recommendations for New Dealers. Part Numbers, Quantities and Prices.	TC793
1969	23-Jan-69	Current back orders with Tri-Cor.	TC794
1969	30-Jan-69	Bell Star Helmet, New Accessories and Visors.	TC795
1969	31-Jan-69	Price Reductions on Tri-Cor Helmets and Bulk order Discounts.	TC796
1969	10-Mar-69	T150 Trident Gasket Set, American Made Gaskets.	TC797
1969	10-Mar-69	Service Tools from Tri-Cor, new Items at Discounted Prices.	TC798

1969	07-Apr-69	Corrections for the 1969 TR25W Parts Catalogue. Important Corrections and Additions.	TC799
1969	08-Apr-69	Special Workshop Tools for Triumph Models. New Tools for the Triple and Twins.	TC801
1969	15-May-69	New Clutch Cable for the Triumph Trident 750cc Three. Nylon Lined Clutch Cable.	TC802
1969	25-Jun-69	Additional Corrections for the T150 Parts Catalogue. Important Additions and Corrections.	TC803
1969	30-Jun-69	Special Mid-Season Bargains on Parts and Accessories. Extensive List of Old Stock Parts.	TC804
1969	28-Jul-69	New Workshop Tools. Includes Lubrication Test Set, Swing Arm Bush Tool, Race Camshaft for TR25W (Gary Fisher).	TC805
1969	29-Jul-69	Bolt, Nut, Stud and Set screw Sizes in UNF and UNC Threads. With Part Numbers 14-0101 etc. (Important)	TC806
1969	14-Aug-69	Current back orders with Tri-Cor.	TC807
1969	15-Sep-69	Castrol Oils available through Tri-Cor. Price List.	TC808
1969	10-Oct-69	Control Cables fitted to all Triumph Motorcycles (US Models) up to 1970. Part Numbers	TC809
1969	10-Oct-69	Pistons and Rings in Stock at Tri-Cor for all models. Part Numbers.	TC810
1969	10-Oct-69	Lucas Stators and Rotors fitted to all Triumph Motorcycles (US Models) 1954 to 1970.	TC811
1969	23-Oct-69	Gear Parts Chart for all Models from 1960. Part Numbers for all Gears up to 1970 Models.	TC812
1969	253	Service Tools (Revised 1969) All	875
1969	300	All Models Tachometer Drive Box Left Hand Thread	916
1969	306	Flexible Handlebar mountings on 650cc Machines from NC02040	1100
1969	308	TR25W Cylinder liner retention. Bulletin 308	553
1969	309	Lubrication of Lucas Auto-Advance / Retard Mechanisms	922
1969	312	All Twins Improved Fork Action with Shuttle Valves. Modification	925
1969	313	TR25W Crankshaft Conversion to Roller Bearing from No: 12468	926
1969	316	Service Exchange Scheme	927
1969	317	Connecting Rod Big End Nuts -'B' Range All Models. 22ft lbs	928
1969	318	TR25W Valve Gear - (Valve Spring Top Collar Collet Angles)	929
1969	322	Front Mudguards - Rationalisation. H3882 only to be available!	930
1969	323	Piston Ring Gaps - 650cc Models. Gap Now 15-20 thou	931
1969	324	B' & 'C' All Models Push Rod Cover Tube Oil Sealing 1969-70 Models	932
1969	325	TR25W Lucas Automatic Advance and Retard Unit Springs	933
1969	326	USA Rear Number Plate Support Bracket fitted from October 1969	934
1969	327	Trident (T150) Rocker Adjuster Pins. New Part	935
1970	328	TR25W Valve Timing Markings for 1970 Models	936
1970	329	650cc and 750cc. Gearbox 3rd Gear Ratios and Selector Forks	937
1970	330	Camshafts for Trophy 250cc TR25W	938
1970	332	Rear Wheels. Unified Threads and Rim Sizes on 'B' & 'C' Range Models.	939

1970	334	All Models 1946 to 1970, Spokes, Nipples, Finish, Gauge and Head Angles. (Important)	940
1970	335	350cc & 500cc All Models Improved Gearbox Camplate Spare	941
1970	336	Silencers, 350-500cc Models. Only Later Versions Available as Spares	942
1970	337	1970 Carburettor Settings for the New Air Filter	943
1970	339	Service Exchange Replacement Units - Revised Prices	944
1970	340	Carburettor Jet Size Increase - Personal Export Machines	945
1970	342	"B" Range New Stronger Swinging Arm Assembly F10045	946
1970	343	TR6R Exhaust pipes -(Pommels now UNC, not CEI)	947
1970	345	TR25W Oil Pump Priming Procedure	948
1970	346	Contact Breaker Locking Screws - All Models	949
1970	347	Twin Horn Mounting Brackets - T120, T120R	950
1970	348	Battery vent pipe -'B' &'C' All Models	951
1970	349	U.K. Personal Export Scheme -'Warranty Passport' (Europe Distr)	952
1970	350	U.K. Personal Export Scheme -'Warranty Passport' (Home Distr)	953
1970	353	Gearbox Selector Forks and Camplate -'B' All Models	954
1970	353	Gearbox Selector Forks and Camplate -'B' All Models (Additional)	955
1970	354	Police Forces - Speedometer Calibration with Dunlop K81 Tyres	956
1970	355	Loctite Plastic Gasket (Silicone Sealer)	957
1970	356	TR25W Front Brake Cable Guide.	958
1970	358	Sparking plugs -'B' All models and T150 (Champion N3)	959
1970	360	Rear brake Drum All models now UNF	960
1970	361	T150 Trident Primary Chain Shock Absorber Assembly. Warranty Problem	961
1971	310	Camshafts Identification, Type and Usage (Revised)	924
1971	363	"C" Range Models Wiring Arrangement (Indicators)	963
1971	364	Police TR6P Machines - (Alternator)	964
1971	366	Twin Leading Shoe Front Brake. Warranty Recall	965
1971	367	Fuel Feed Problems - Twins and Triples B,C,T150	966
1971	368	T25SS Blazer, T25T Trail Blazer Oil Pipe Retention	967
1971	369	1971 Replacement Parts Catalogue Binders	968
1971	370	Service Exchange Scheme no Longer available on 8 Stud Heads	969
1971	372	Service Literature available	970
1971	373	1971 Rear brake efficiency - T150,'B' All models and T25. Modification	971
1971	374	Personal Export Scheme 1971 -Warranty Passport (U. K. Dealers)	972

1971	375	Personal Export Scheme 1971 -Warranty Passport (Euro Dealers)	973
1971	376	BSA Divisional Part Number Pre-Fixing replaces Triumph Codes	974
1971	377	Replacement silencers E4157 and E4158 -'C' All models	975
1971	378	All Models Front Brake Cable Stop Switch. New Cable. Modification	976
1971	379	Service Replacement Engine Units - UK Dealers	977
1971	380	Guarantee Replacement Engine Units Export Dealers	978
1971	381	250 cc Machines Replacement Oil Pump	979
1971	382	All 'B' Range Models New Oil Reservoir Filter	980
1971	383	Gearbox High Gear Bearing - Five Speed - 650cc and 750cc Twins	981
1971	384	Gearbox Camplate Supersession -'B' Range All Models	982
1971	385	Push-In Exhaust Pipes - 650cc Not Yet Fitted to 1972 Models	983
1971	386	1971 Telescopic Fork Wallchart Available	984
1971	387	Gearbox Quadrant Location Tool - Five Speed Gearbox Only	985
1971	388	Replacement Front Frame F7843 No Longer Available	986
1971	390	Replacement Bushes - All 5 Speed Gearboxes	987
1971	391	QD Rear Nub -'B' Range - Models up to 1970 no Longer Available in CEI	988
1971	392	5 Speed Gearboxes Wall Chart Available	989
1971	394	Rear Brake Shoe Assemblies 750 & 650cc 1971/72 Models	991
1971	395	Rear Chain Adjustment (Increase Slack)- 250 Single Cylinder Models	992
1971	USA 1/71	Brake Return Spring 8" Brake	1048
1971	USA 1/71	T25, T25SS Oil Change Recommendations	1049
1971	USA 1/71	Cylinder Head Bolts TR6C, TR6R, T120R New Form on 1971 Models	1050
1971	USA 1/71	T150 High Speed Operation 'Caution'. Open Both Pet Cocks	1051
1971	USA 10/71	Oil Seepage at Rocker box All Twins. Permatex/Loctite	1079
1971	USA 10/71	T25 Zener Diode Installation	1081
1971	USA 11/71	Piston Ring Replacement 'B' All models. Preparing Cylinders	1082
1971	USA 12/71	T25 Improved Fork Seal. Dismantling and Fitting Instructions	1084
1971	USA 12/71	Primary Chain Oiler All Models. Use of Adhesive	1085
1971	USA 13/71	Abnormal Vibration T25. Remedies	1087
1971	USA 13/71	Air filters 'B' Range All models Sealing for Off Road Use.	1088
1971	USA 13/71	T150 Improved Fork Seal for 1972 Models. Dismantling and Fitting Instructions	1089
1971	USA 14/71	Broken Tappets T25. Checking Valve Springs	1090
1971	USA 14/71	Gearbox Camplate 'C' Range All models. Camplate Drawing	1091
1971	USA 14/71	Abnormal Vibration T150. Remedies	1092

1971	USA 15/71	Improved Oil Pipes T25. Thicker Tubing Used	1093
1971	USA 15/71	American Made Replacement Gears all 'B' Range Models	1094
1971	USA 15/71	American Made Replacement Gears B all 'B' Range Models Revised	1095
1971	USA 15/71	T120V 5 Speed Gearbox Overhaul	1096
1971	USA 16/71	All Models "B" Range Improved Fork Seal. Dismantling and Fitting	1097
1971	USA 17/71	Abnormal Vibration All Twins. Remedies	1098
1971	USA 18/71	T120RV 5 Speed Gearbox Overhaul	1099
1971	USA 2/71	T25T, T25SS Oil Return Pipe Too Short	1052
1971	USA 2/71	Broken Battery Cases TR6, T120	1053
1971	USA 2/71	Battery Installation T25T, T25SS	1055
1971	USA 3/71	Brake Burnishing Procedure T150	1057
1971	USA 4/71	Brake Burnishing Procedure T25T, T25SS	1058
1971	USA 4/71	Checking Oil Level in OIF Reservoir TR6, T120	1059
1971	USA 4/71	T150 Front Brake Cable Stoplight Switch T150 Modification	1060
1971	USA 5/71	T25T, T25SS Oil Pipe Chafing	1061
1971	USA 5/71	Brake Burnishing Procedure TR6, T120	1062
1971	USA 5/71	T150 Sump Filter Cover. Fitting Note	1063
1971	USA 6/71	Cleaning. Do Not Use Service Station Pressure Washer	1064
1971	USA 6/71	TR6 T120 Lighting, Full Time Use. Modification	1066
1971	USA 6/71	Fork Top Cap Nut Sealing T150 using Permatex/Loctite	1067
1971	USA 7/71	500 Mile Service Check	1068
1971	USA 7/71	T 25 Gear change Quadrant Adjustment after DE9340	1069
1971	USA 7/71	TR6 T120 Front Brake Cable Stoplight Switch Modification	1070
1971	USA 7/71	Brake Rod Spacer T150 New Washer to Relieve Stresses	1071
1971	USA 8/71	T25 Front Brake Cable Stoplight Switch Modification	1072
1971	USA 8/71	Top Cap Nut Sealing TR6, T120 using Permatex/Loctite	1073
1971	USA 8/71	T150 Zener Diode Installation with Heat Transfer Compound	1074
1971	USA 8/71	Top Cap Nut Sealing T25T, T25SS using Permatex/Loctite	1075
1971	USA 9/71	TR6, T120 Zener Diode Installation with Heat Transfer Compound	1076
1971	USA 9/71	T150 Rocker Arm/Pushrod Identification from AE00319	1077
1972	393	Lucas PUZ5A Batteries - Battery Vent Outlet. Warranty	990
1972	396	Primary Chaincase Covers 650cc twins. Early Versions No Longer Available	993
1972	397	All 'C' Range Models Oil Tanks. Only new Version Available as Spares	994

1972	398	Rear Frame Revised Components for Lowered Frame from GG50414	995
1972	399	Rear brake cam - 650cc Models Only. CEI Only	996
1972	400	Front Mudguard Stays - "B" All Models (650cc twins)	997
1972	401	Rear Chain guard (650cc twins). Warranty	998
1972	402	T120 Cylinder Head and Carb Adaptors - T120 Models from KE00001	999
1972	403	Replacement Front Frame - 650cc Models F7371 No Longer Available	1000
1972	404	Leg shields "B" Range. Police models. Eyebolts	1001
1972	405	Battery Connections "C" Range. Police Models Only	1002
1972	407	T150 750CC Trident models only. Oversize Valve Guides	1003
1972	408	T25 250CC. Oversize Valve Guides	1004
1972	409	Cylinder Head Bolts "B" Range Models. New System from KE00001	1005
1972	410	Primary Chain Adjustment "B" Range Models. New Tool	1006
1972	411	Frame - Petrol Tank Mounting -'B' All Models (650cc Models Only) CG50414	1007
1972	412	Wiring Diagram "B" Range Model Wallchart. Available	1008
1972	413	Extractor for Camwheels "B" Range Models (650cc Models Only) CG50464	1009
1972	414	Gearbox - 5 Speed - All Models. New Parts	1010
1972	415	Frame -'B' Range Models (650cc models). Seat Adaptor Plate Available	1011
1972	416	Connecting Rods - "C" Models. E8834 Discontinued	1012
1972	417	Part Number Rationalization. Conversion Chart	1013
1972	417A	Part Number Rationalization (Additional)	1014
1972	418	Connecting Rods - 250 Model Only. Rationalisation	1015
1972	418A	Connecting Rods - 250 Model Only Amendment	1016
1972	419	Gearbox Sprocket Nut Spanner - 5 Speed Models	1017
1972	421	Trident Crankcase Assemblies - All 750cc 3 Cylinder Trident Models. New Part	1018
1972	422	Rear Brake Drum -"B" & "C" Models (500 & 650cc Models). UNF only	1019
1973	423	Piston Assemblies - All 750cc Twin Cylinders. Models. New Size from XH22019	1020
1973	423A	Piston Assemblies - All 750cc Twin Cylinders. Models Amendment	1021
1973	424	Timing Gears - All 750cc Twins -"B" Range Models. Marks Explained.	1022
1973	425	Carburettor Induction Tube - 1972 TR5T Trophy Trail Models Only. Modification.	1023
1973	427	Rear Brake Operating Arm -All 1973 T150 machines T150. Modification	1024
1973	428	Currently Available Service Literature All	1025
1973	429	New Trident Crankshaft - All 750cc Three Cylinder Models. From PG01603	1026
1973	430	Hydraulic Front Brake Lockheed Parts -T140V / TR7RV and T150	1027

1973	430A	Models Hydraulic Front Brake Illustration -T140V / TR7RV and T150	1028
1973	431	Cap Washer for Hydraulic Reservoir - All Disc Brake Models	1029
1973	432	Cylinder Block and Piston Grading -All 76mm 750cc Twins	1030
1973	433	Pressure Release Valve. Two Types	1031
1973	434	Warranty Credit Claims - V.A.T.	1032
1973	435	Cylinder Block. All 76mm bore 750cc Models to UNF	1033
1973	436	Price List Service Replacement Parts	1034
1973	437	Sump Filter Plug. Fit O Ring -"B" Range Models	1035
1973	438	T140V Front Mudguard Stay Support Bracket - T140V Only NH17668	1036